
From: Larry Visoski [REDACTED]
Sent: Tuesday, March 29, 2016 7:51 PM
To: Je vacation
Subject: Joe's G550 had 5 cabin Windows only!

Jeffrey

Joe will fwd Non Professional interior photos of the aircraft,. He will provide a document that you can adjust the price, and options, similar to his email ,
he asked for 1 or 2 days so seller can approve the doc.

Joe's G550 has HUD and EVS installed

Cabin Windows:

As I look closer at photos,

Correct me if I'm wrong, I noticed the Fwd galley is so long it covers 2 cabin Windows on each side of Fuselage!
Appears the left side fuselage has Fwd Lav which utilizes the fwd most cabin=window in this Lav, and Right side Galley covers the Two fwd cabin Windows,=This could be a major change to completely redesign the fwd Galley floor plan, to take advantage of the 7 cabin windows

To move the fwd Lav to right side of aircraft could be a big undertaking, since the external LAV service port is most likely located on the left side fuselage,.

Avpro plane appears to have much smaller Crew Size LAV fwd and located on Right side of fuselage Not taking up window space.,

Sent from my iPhone=?xml version=.0" encoding=UTF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>84839</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1459281047</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>600022</string>
</dict>
</plist>