
From: jeffrey E. <jeevacation@gmail.com>
Sent: Monday, March 21, 2016 12:27 PM
To: Larry Visoski
Subject: Re:

under engines said it was due at 3000 hrs

<=iv class="gmail_extra">

On Mon, Mar 21, 2016 at 8:24 AM, Larry Visoski <[REDACTED]>

Yes, i'll have Pete investigate those areas in the Aircraft records,

=here did you see the mention of hot section?

Sent from my iPhone

On Mar 21, 2016, at 8:21 AM, jeffrey E. <jeevacation@gmail.com <mailto:j=evacation@gmail.com>> wrote=

landing gear= headliner removal. hot section. brakes. corrosion, all checks=. pitting . ?

--

=A0 please note

The information=contained in this communication is confidential, may be attorney-client=privileged, may constitute inside information, and is intended only for=br>the use of the addressee. It is the property of JEE

Unauthorized =se, disclosure or copying of this communication or any part thereof is =trictly prohibited and may be unlawful. If you have received this co=munication in error, please notify us immediately by return e-mail or b= e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and all copies the=eof, including all attachments. copyright -all rights reserved

--
=C2 please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved