

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Wednesday, April 4, 2018 10:30 PM  
**To:** Larry Visoski  
**Subject:** Re: 5173 G550 / N212JE upgrade mods

we did , he will get us numbrs nexgt week,♦=A0 need new carpet. long lead time. 1 month down. =br>

On Thu,=Apr 5, 2018 at 12:10 AM, Larry Visoski <lvjet@aol.com> wrote:

=div>This is the email i sent to Eric today, outlining your request for a q=ote,.  
I didn't get a reply back,. I'm sure Eric =ill discuss with you directly. I tried to cover all you concerns, so nothi=g is left out,. Including arm rest covers for Capt VIP chairs in PAX cabin=

Thx  
larry

Sent from my iPad

Begin =orwarded message:

From:=Larry Visoski <[REDACTED]<mailto:[REDACTED]>>  
Date: April 4, 2018 at 6:08:04 PM GMT+2  
To= Eric Roth <=Roth@intljet.com <mailto:ERoth@intljet.com>>  
Cc: Larry [REDACTED] <mailto:[REDACTED]>, Jay Massar [REDACTED] =ileen  
McDowell [REDACTED] <mailto:[REDACTED]>  
Subject: 5173 G550 / N212JE =pgrade mods

Hello Eric, and  
Jay, Eileen.=

Jeffrey would like you to quote the foll=wing:

0-did Eileen locate availability of=the Divan materials JE selected for Divan and Pillows etc?

1-Remake the Galley sink cutting board plug in lightweigh= material, current plug weighs 6lbs,

2-Re=Veneer Aft LAV seat in veneer, as oppose to Leather seat currently install=d.

3-Veneer sliding cover for Fwd Monitor=

4-install LED up and down wash lights in=Cabin, Galley and aft LAV.,

Plug and Play style. (Pls conf=rm if LED lights are capable of DIM function?

<=pan>5-re Veneer fwd Cabin side of Pocket door, for Clean appearance, NO pe=p hole showing Vacant or Occupied slide opening.

<=r>6-Re-veneer Cabin side of AFT LAV door to eliminate the Vacant / O=cupied display.

7-New material on side DA=O window panels and Down wash valance, removing all the small Passenger TV=monitors for DADO panels,

8-another alter=ative is to re do the entire drink rail, take out all swithces excep= for shade, no need for headphone/video jack etc.

not sur= if "call button" is required. or not, can't imagi= it is.

9-see photos below, notice the ta=les where removed, but Dado panel cutout still exists, and Veneer is not u=iform with the rest of drink ledge,

please remove bulge, =C2♦re-Venner the area of Drink ledge and remove the bulge from Side Dado=Panel and recover with fabric for a clean stream line look . L/H and=R/H sides.

10-Arm rest covers for Capt ch=irs like you made for GIV seats.

11-Loose=Aft Lav drain valve for VIP sink,,, JE requests Rubber wrap / Grip around =he handle of the sink drain Knob,, its hard to turn as we know, when your =ands are wet.

12-JE asked if he needed t= change the carpet with Divan mods you are contemplating?,,, this is just = reminder item, I'm trying to keep a Precise list of To Due items =e can work from

=/div>

</=pan>

Sent from my iPad

Sent from my iPa=

--

please n=te

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property=of

JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com) <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved