

---

**From:** Ann Rodriguez <[REDACTED]>  
**Sent:** Saturday, October 31, 2015 10:01 PM  
**To:** Jeffrey E.  
**Cc:** Rich Kahn  
**Subject:** Transformer update  
**Attachments:** image1.JPG; Untitled attachment 00227.txt; image2.JPG; Untitled attachment 00230.txt; image3.JPG; Untitled attachment 00233.txt; image4.JPG; Untitled attachment 00236.txt; image5.JPG; Untitled attachment 00239.txt; image6.JPG; Untitled attachment 00242.txt; image7.JPG; Untitled attachment 00245.txt; image8.JPG; Untitled attachment 00248.txt; image9.JPG; Untitled attachment 00251.txt; image10.JPG; Untitled attachment 00254.txt

:( Not good.

They installed the new transformer today and when they fired it up the trans=ormer blew the power line on St. Thomas again.

Danny said we might have an underwater issue. I was waiting for his report t= send to you but I haven't received anything as yet.

Mr. Bryan is saying that are transformer is no good anymore. (It still looks=brand new to me.) photos attached.