

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Friday, November 6, 2015 12:24 AM  
**To:** Ann Rodriquez; Richard Kahn  
**Subject:** Re: Transformer: Mr. Felix Rey

lets find one asap

On Thu, Nov 5, 2015 at 7:19 PM, Ann Rodriquez [REDACTED]  
[REDACTED] wrote:

----- Forwarded message -----

From: Felix S. Rey [REDACTED]  
Date: Thu, Nov 5, 2015 at 5:04 PM  
Subject: RE:LSJE, LLC - November 5, 2015  
To: Daphne Wallace [REDACTED]

=br>

The 1500kva transformer was tested with TTR test. The B bushing on the transformer tested good but with high amp=. The A bushing was tested and the D tap for that side of the transformer failed. We believe the 1500kva is much too large a transformer for the load that the island is using. Your meter at the site is showing less than 200amps per phase. A 500kva is more a better size for the island at this point. As for the meter base we are still trying to get one.

<=div>

--

=C2 please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

