

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Wednesday, April 4, 2018 12:11 PM  
**To:** Larry Visoski  
**Subject:** Re: Price quote

adjust rear table. . does exhaust fan wo=k in coffee cabinet.? larry for eric. remake the l=d to the galley sink in lighthead material. ♦=AO we will also re veneer lav seat. does not have =o be a match. and cover for monitor sliding would have t= match. another alterntice is to re do the entire drink rail . =take out all swithces except for shade. no need fo= headphone video jack . etc. not sure if call button is requir=d. or not. cant imagin it is.

On Wed, Apr 4, 2018 at 2:06 PM, Larry Visoski [REDACTED] <mailto:[REDACTED]> > wrote:

Jeffrey

How does this look? If you approve, I'll send a copy to Eric and Ru=ty to quote?  
Should i add any more?

Eric,

Jeffery asked if you could price quote the following items.,

1- install up and down wash LED lights in Cabin, Galley and aft LAV.,  
Plug and Play style. (Pls confirm if LED lights are capable of DIM function=)

2-re Veneer Cabin side of Pocket door, for Clean appearance, NO peep hole o= Vacant or Occupied sign.. clean look.

3-Re-veneer Cabin side of AFT LAV door to eliminate the Vacant / Occupied hole.

4-New material on side window panels and Down wash valance.

5-see photos below, notice the tables where removed, but Dado panel cutout =till exists, and Veneer is not uniform with the rest of drink ledge,

please remove bulge, re-Venner the area of Drink ledge and remove the=bulge from Side Dado Panel and recover with fabric for a clean stream line=look . L/H and R/H sides.

Sent from my iPad

Sent from my iPad

conversation-id 10799 date-last-viewed 0 date-received 1522843880 flags 8590195713 gmail-label-ids 7 remote-id 809588