

---

**From:** jeffrey E. <[REDACTED]>  
**Sent:** Saturday, June 27, 2015 8:10 PM  
**To:** Larry Visoski  
**Subject:** Re: GIV AC system

but the air would have been going overboard if the water separator was not working or the bypass doors were not fixed

On Sat, Jun 27, 2015 at 3:41 PM, Larry Visoski <[REDACTED]> <mailto:lvjet@aol.com> > wrote:

Also note, we have closed both bleed switches, both Packs and tried flying unpressurized during our early days of trouble shooting if memory serves correct?

I believe we were flying at 10,000 ft on approach to PBI with Billy on board.,

See attachment for color system schematic

Sent from my iPhone

</div>--

=A0 please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [\[REDACTED\]](mailto:[REDACTED]) target="\_blank">jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--001a11c2443e79f0ec0519857050-- conversation-id 112238 date-last-viewed 0 date-received 1435435791 flags 8590195713 gmail-label-ids 7 remote-id 520360