
From: Larry Visoski [REDACTED] >
Sent: Thursday, May 7, 2015 5:14 PM
To: Je vacation
Subject: Update
Attachments: IMG_2896.JPG; Untitled attachment 00580.txt

I'm doing high power runs now,.

So far TGT validation check has determined that Left engine has Ground Short=on TGT system

We have to locate short,, if it's engine external should be easy repair,. If=it's engine Internal,, requires thrust reversal and engine removal,, Rolls Royce and Corporate Care will evaluate after all checks are complete

Will update you after Engine high power runs