
From: Larry Visoski <████████>
Sent: Thursday, February 26, 2015 1:14 AM
To: jeffrey E.
Subject: Re: Flagpole

Yes,. Jermaine can explain, he informed it happen some time ago,

Sent from my iPhone

On Feb 25, 2015, at 9:12 PM, jeffrey E. <jeevacation@gmail.com <mailto:jeevacation@gmail.com>> wrote:

roll down hill?

On Wed, Feb 25, 2015 at 7:28 PM, Larry Visoski <████████ <mailto:lvjet@aol.com>> wrote:

Found blown tweeter on North side of pool, speaker sounds flat,. Tried other speaker to prove its speaker, Jermaine indicated Speaker fell down hill.,

Found tweeter wire not connected to amp.,

Reduced Gain on Mid amps,. Was overpowering tweeters.,

Buzz in system could main ground to Cabana power,. Since buzz is not reduced with volume,. Only amp gain reduces buzz.,

I think we should replace the entire blown speaker, since it rolled down the hill?

Let me know if it sounds any better?

Thx

Sent from my iPhone

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved