
From: Larry Visoski <[REDACTED]>
Sent: Thursday, February 26, 2015 8:14 PM
To: Je vacation
Subject: Fuel leak

We have Fuel leak in right hand wing, pressure fuel line Searching for oring part number should take 4 hours to change,
Will keep u updated

Sent from my iPhone

```
<?xml version="1.0" encoding="UTF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version="1.0">
<dict>
  <key>conversation-id</key>
  <integer>123788</integer>
  <key>date-last-viewed</key>
  <integer>0</integer>
  <key>date-received</key>
  <integer>1424981613</integer>
  <key>flags</key>
  <integer>8590195713</integer>
  <key>gmail-label-ids</key>
  <array>
    <integer>2</integer>
  </array>
  <key>remote-id</key>
  <string>485770</string>
</dict>
</plist>
```