

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Tuesday, February 3, 2015 1:52 AM  
**To:** Je vacation  
**Subject:** Flaps

Flaps went to 20degree with aux pump only when I got to the plane,. I didn't=have to hang on the flap., I'm good to go to Westfield at sunrise tomorrow morning,.  
I'll keep you updated

Gutt tell me it's flap track rigging., not actuator., we should be fine for W=d departure even if we change the outboard actuator

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">  
<plist version=.0">  
<dict>  
    <key>conversation-id</key>  
    <integer>126079</integer>  
    <key>date-last-viewed</key>  
    <integer>0</integer>  
    <key>date-received</key>  
    <integer>1422928316</integer>  
    <key>flags</key>  
    <integer>8590195713</integer>  
    <key>gmail-label-ids</key>  
    <array>  
        <integer>2</integer>  
    </array>  
    <key>remote-id</key>  
    <string>478717</string>  
</dict>  
</plist>