
From: Richard Kahn <[REDACTED]>
Sent: Friday, March 2, 2018 12:33 AM
To: Jeffrey Epstein
Subject: Fwd: LSJ Rimco Report.pdf

Richard Kahn
HBRK Associates =nc.
575 Lexington =venue, 4th Floor
New York, NY =0022
tel = [REDACTED]
fax = [REDACTED]
cell = [REDACTED]

Begin forwarded message:

From: =/b>Bill Hague <[REDACTED]>

Subject: =/b>Re: LSJ Rimco =eport.pdf

Date: =/b>March 1, 2018 at 7:11:00 PM =ST

To: =/b>Richard Kahn <[REDACTED]>

Cc: Brice Gordon <zdc.rt41@gmail.com>, =ichael Glidden <[REDACTED]>
<mailto:[REDACTED]> >

Well.

No surprises here.

The outstanding issue I see here has to do the =egger test (insulation test). It should be tested BEFORE, any work is =one to the generator end windings.

A subsequent test, after the work is done, will =hen let us know if this cleaning did any HARM to the operational =unction of the units during the cleaning, in a before and after factual =est. It will eliminate any he said he said and finger =ointing.

Thats my opinion of the report.

I look forward to your insights. =nbsp;

On Mar 1, 2018, at 19:53, Richard Kahn <[REDACTED]> wrote:

Richard Kahn
HBRK Associates Inc.
575 Lexington Avenue, 4th Floor
New York, NY 10022
tel [REDACTED]
fax [REDACTED]
cell [REDACTED]

Begin forwarded message:

From: Russell Hernandez <[REDACTED]>

Subject: LSJ Rimco Report.pdf

Date: March 1, 2018 at 6:46:43 PM EST

To: "jeffrey E." <jeevacation@gmail.com <mailto:jeevacation@gmail.com>>,
<mailto:[REDACTED]>

Russell Hernandez

<LSJ Rimco Report.pdf>

=