
From: Jeffrey Epstein <jeevacation@gmail.com>
Sent: Wednesday, February 27, 2013 9:14 PM
To: [REDACTED]
Subject: Re: GIV prebuy items.,

yes

On Wed, Feb 27, 2013 at 3:45 PM, [REDACTED] <mailto:[REDACTED]> wrote:

Jeffrey,

I have compiled the following list for prebuy for serial # 1085 GIV which should be attractive to Dennis with our \$6M offer., I ha=e excluded Landing Gear and included my own approach for external inspection=20 "Gulfstream factory preflight" this should lead Dennis to believe=we are not accomplishing the Gulfstream Full airframe Survey, however I will have Gulfstream complete a full walk around of exterior and rear equipment bay=20 which requires a maintenance person to visually inspected the entire exterior fuselage for any discrepancies or un-airworthy items.,I also incl=ed a visual inspection for under fwd and aft lavatories, checking for corrosion =nd compliance with ASC469 (water Line inspection).

I would like to get Sean Lancaster's opinion and Sean Brown (Gulfs=ream Maintenance lead) on this inspection to verify I have not overlooked an=20 area, and we have inspected area's so I'm able to maximize our repa=r prebuy.

May I fwd this to Sean L and Sean B for their opinion?

*** I'm not sure how much time Sean Lancaster will devote to giv=ng us a real answer since we still owe Bristol for S76 sales invoice (approx \$11,900) Sean is leery of getting to involved in helping us.

I focused on the due list which would address maintenance items due up=20 until December 2013.

Gulfstream Test Flight with Gulfstream Test pilots

APU Borescope inspection

Engine borescope and engine runs functional tests

134401 Comply with Avionics inventory

100310 Check Airworthiness Directives

100320 Check Service Bulletins

191108 Aircraft status report review

231001 Avionics Ramp functional test

531007 FS85 BulkHead inspection

532007 Fwd Cabin below floor

532009 Mid Cabin below floor

551019 Horizontal Stabilizer / Elevator L/H inspection

551020 Horizontal Stabilizer / Elevator R/H inspection

275009 Flap Actuator Yoke L/H inboard inspection

275010 Flap Actuator Yoke R/H inboard inspection

275011 Flap Actuator Yoke L/H Outboard inspection

275012 Flap Actuator Yoke R/H Outboard inspection

275027 Flap Actuator bushing L/H lube

275028 Flap Actuator bushing R/H lube

270101 Stall Barrier angle of Attack functional test

272038 Rudder Peddle lube

280005 Fuel control functional test

303005 Pitot Heat Functional test

551023 Horizontal Stabilizer/ Elevator L/H internal /external inspection

551024 Horizontal Stabilizer / Elevator R=H internal / External inspection =/span>

553005 Vertical Stabilizer / Rudder External inspection

553007 Vertical Stabilizer / Rudder internal inspection

571011 Wing Front Beam Hi Lite L/H inspection

571012 Wing Front Beam Hi Lite R/H inspection

571025 Wing internal L/H inspection

571026 Wing internal R/H inspection

251114 Pilot / Copilot seat lube

262045 Fire Bottle Hydrostatic test L/H

262050 Fire Bottle Hydrostatic test R/H

Visual inspection under fwd and aft lavatories in cabin

Comply with full Gulfstream pre-flight inspection and service

-- =br>*****

The info=mation contained in this communication is confidential, may be attorney=client privileged, may constitute inside information, and is intended only for the use of the a=dressee. It is the property of Jeffrey Epstein Unauthorized use, di=closure or copying of this communication or any part thereof is strictl= prohibited and may be unlawful. If you have received this communication in error, p=ease notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, =nd destroy this communication and all copies thereof, including all attachm=nts. copyright -all rights reserved