
From: Russell Hernandez [REDACTED]
Sent: Monday, February 5, 2018 7:31 PM
To: Cashkim Bussue
Cc: Jeffrey Epstein; Brice Gordon; Richard Kahn; Ann Rodriquez; Mark Libonati
Subject: Re: Man Hole

great thank you could you please confirm that the rebar was drilled into the existing concrete i have added mark (shark) from ASC as well

we can see the rebar in the photo but can't see the connection

also every block should have rebar=C2

thank you

On Mon, Feb 5, 2018 at 2:21 PM, Cashkim Bussue <[REDACTED]> wrote:

<https://drive.google.com/file/d/18WWIT04qj7huyTX2PAXY7u2fhYnp2bDi/view?usp=drive_web>

IMG_3619.JPG <https://drive.google.com/file/d/1yvseoUFlzwZE3x6wbP=wmWSxsbk9eGy/view?usp=drive_web>

=8B

<https://ssl.gstatic.com/docs/doclist/images/icon_10_generic_list.png> IMG_3620.JPG

<https://drive.google.com/file/d/1RGL1jaoQP8q4hkxCHsC0mC-lcB0kEDWQ/view?usp=drive_web>

<https://drive.google.com/file/d/1YjX7VG6RihY=Nxdbgay3gwakq4cg3g9A/view?usp=drive_web>

<https://ssl.gstatic.com/docs/doclist/images/icon_10_generic_list.png> IMG_3624.JPG

IMG_3625.JPG

<https://drive.google.com/file/d/1V7ew0o2DRmtwaBLmutglgKp8tRWFeWoC/view?usp=drive_web>

IMG_3626.JPG

<https://drive.google.com/file/d/1M9ezd=4d3OodRGrNGATzRv3bdH_61ENI/view?usp=drive_web>