

---

**From:** Ann Rodriguez [REDACTED] >  
**Sent:** Friday, February 2, 2018 12:40 AM  
**To:** jeevacation@gmail.com  
**Subject:** 97 Smithbay: Cistern 1  
**Attachments:** IMG\_7278.jpg; Untitled attachment 00080.txt; IMG\_7279.jpg; Untitled attachment 00083.txt; IMG\_7280.jpg; Untitled attachment 00086.txt; IMG\_7281.jpg; Untitled attachment 00089.txt; IMG\_7282.jpg; Untitled attachment 00092.txt; IMG\_7283.jpg; Untitled attachment 00095.txt; IMG\_7284.jpg; Untitled attachment 00098.txt; IMG\_7285.jpg; Untitled attachment 00101.txt; IMG\_7286.jpg; Untitled attachment 00104.txt; IMG\_7287.jpg; Untitled attachment 00107.txt; IMG\_7288.jpg; Untitled attachment 00110.txt

Hey Bossman,

Mr. Colbert said the Cistern need to be cleaned out and chipped out before he can seal and coat inside.

The previous owners plastered a poured Cistern instead of sealing it now the=plaster is cracking on the walls. The plaster on the ceiling is already fal=ing but no leaks☺just really disgusting down there

Cistern 2 & 3 are plastered shut but we're breaking it open tomorrow=morning