
From: emad hanna <[REDACTED]>
Sent: Saturday, May 28, 2011 2:14 AM
To: Jeffrey Epstein
Subject: Fwd: Hydroseeder

Jeffrey,

I saw Daphne's e mail with photo's and =otice a few items are waiting for equipment.
And I was =peaking to Gary about the condition of the equipment and he tells me =hat he will be looking to rent out
some machine because several of the =SJ machines are down.
There seems to be a low level of =outine preventive maintenance and it ends up costing more in the long =un with
machine being down and work slowing down and machine's being =ented.

Below is an example of work needed to =e done for some time on the hydroseeder. Take a look at the photo's =elow

Thank =ou

Emad Hanna
Project Controller
HBRK Associates
[REDACTED]

Begin forwarded message:

From: Joseph Igala <igala@mac.com>

Date: May 27, 2011 =:19:28 PM EDT

To: McGuinness Arron <arranlsj@yahoo.com>
</=iv>
Cc: Gordon Brice <bgordon.lsj@gmail.com>, =ary Kerney <gkerney@landmarklandco.com>; Hanna Emad
<emad.hanna01@gmail.com>
<=span>
Subject: Hydroseeder

Good =fternoon,

I am sending these pictures as a reminder that =omething has to be done to repair our Hydro-Seeder. Arron and I have =spoken about it several times, but with rainy season coming up, we Need =o get it in shape. Especially considering that the Boss has =xpressed several times in person and via phone and email that he =ntends to have Us (Landscaping Dept.) Hydro-Seed "The Whole Island" =uring rainy season, which is upon us.

I feel like it could =possibly be repaired, with some good welding and some new parts, or if =he decision needs to be made to order a new harness, either way, in =t's current state it is unsafe, and close to being out of commission, =hich I'm sure would infuriate the boss, if it was to be down during the =ime he wants it to be in heavy use.

I know we have a lot of =hings going on, however I feel this needs to be made a Priority, and I =m willing to do what ever I can to assist in getting this piece of =ital equipment up to safe, and good working =ondition.

IMG_9415.JPG

=br>

IMG_9416.JPG

=br>

IMG_9417.JPG

=br>

IMG_9418.JPG

=br>

IMG_9419.JPG

=br>

IMG_9420.JPG

=br>

IMG_9421.JPG

=br>

IMG_9422.JPG

=br>Not the best picture, but I have a 3" scar from a gash I received =rom the rusty yoke that was infected due to the rusty metal

IMG_9423.JPG

=br>

IMG_9424.JPG

=br>The Yoke is completely rusted out so we tie it to the =ractor, which is Dangerous to say the least

IMG_9425.JPG

=br>

IMG_9426.JPG

=br>

IMG_9427.JPG

=br>

IMG_9428.JPG

=br>I fear the tank may roll off its harness since the joints of the =races are totally rusted out

IMG_9429.JPG

=br>

IMG_9430.JPG

=br>

IMG_9431.JPG

=br>

IMG_9432.JPG

=br>

IMG_9433.JPG

=br>The rusted wheel well, has punctured two tires.

IMG_9434.JPG

=br>

=