
From: Jeffrey Epstein <jeevacation@gmail.com>
Sent: Saturday, May 28, 2011 2:31 AM
To: emad hanna
Subject: Re: Hydroseeder

i have been asking for thihs for months get it fixed asap

<=iv class="gmail_quote">On Fri, May 27, 2011 at 10:14 PM, emad hanna <emad.hanna01@gmail.com<mailto:emad.hanna01@gmail.com> > wrote:

Jeffrey=

I saw Daphne's e mail with photo's and notice = few items are waiting for equipment.

And I was speaking to Gary about the condition of the equipment and he=tells me that he will be looking to rent out some machine because several =f the LSJ machines are down.

There seems to be a low level of ro=tine preventive maintenance and it ends up costing more in the long run wi=h machine being down and work slowing down and machine's being rented.=div>


Below is an example of work needed to be done for some =ime on the hydroseeder. Take a look at the photo's below

=br>

Thank you

<=pan style="font-size:14px">

Emad Hanna
Project Controller
HBRK Associates



Subject: Hydroseeder

Good Afternoon,

I am sending these picture= as a reminder that Something has to be done to repair our Hydro-Seeder.Arron and I have spoken about it several times, but with rainy season com=ng up, we Need do get it in shape.

Especially considering that the Boss has expressed several times in person and via phone and email that he intends to have Us (Landscaping Dept.) Hydr=Seed "The Whole Island" during rainy season, which is upon us.<=r>

I feel like it could possibly be repaired, with some good welding and some new parts, or if the decision needs to be made to order a new harness.=either way, in it's current state it is unsafe, and close to being out=of commission, which I'm sure would infuriate the boss, if it was to be down during the time he wants it to be in heavy use.

I know we have a lot of things going on, however I feel this needs to =e made a Priority, and I am willing to do what ever I can to assist in get=ing this piece of vital equipment up to safe, and good working condition.<=r>

IMG_9415.JPG

I=G_9416.JPG

IMG_9417.JPG

IMG_941=.JPG

IMG_9419.JPG

IMG_9420.JPG<=r>

IMG_9421.JPG

IMG_9422.JPG

<=r>Not the best picture, but I have a 3" scar from a gash I received from the rusty yoke that was infected due to the rusty metal

IMG_9423.JPG

IMG_9424.JPG

<=r>The Yoke is completely rusted out so we tie it to secure it to the tract=r, which is Dangerous to say the least

IMG_9425.JPG

IMG_9426.JPG

IMG_9427.JPG

IMG_9428.JPG

I fear the tank may roll off its harness since the joints of the braces=are totally rusted out

IMG_9429.JPG

IMG_9430.JPG

IMG_9431.JPG

IMG_9432.JPG

IMG_9433.JPG

The rusted wheel well, has p=nctured two tires.

IMG_9434.JPG

--
*****=
The information contained in this communicati=n is
confidential, may be attorney-client privileged, may
constitute inside i=formation, and is intended only for
the use of the addressee. It is the=property of
Jeffrey Epstein
Unauthorized use, disclosure or copying=of this
communication or any part thereof is strictly prohibited

and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved