
From: Gary Kerney <[REDACTED]>
Sent: Saturday, June 4, 2011 12:48 PM
To: Jeffrey Epstein
Subject: Tub fill

The problem fill comes we believe is the 3/8 faucet Grohe should have a 3/4 faucet, if they have a design you like we should replace it we have a 1" fill line

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>189939</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1307191665</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>6</integer>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>159653</string>
</dict>
</plist>