
From: [REDACTED]
Sent: Thursday, February 2, 2012 2:00 AM
To: Je vacation
Subject: Bell 407

Jeffrey,

Our Bell 407 GPS is inop now, I only have one receiver which supplies GPS signal to both of my maps on the panel, gut feeling, its the antenna,. I'll trouble shoot tomorrow and coordinate with Edwards in Fort Lauderdale.

Our annual inspection is Due March 1st on the Bell, I was going to recommend taking the 407 to Edwards after your departure on the 14th if that is ok with you? Two week down time max, and would have Heli back on St Thomas March 1st for your arrival back to STT.

Is this approved?

Thx,

Larry

Sent via BlackBerry by AT&T

```
<?xml version="1.0" encoding="UTF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version="1.0">
<dict>
    <key>conversation-id</key>
    <integer>210748</integer>
    <key>date-last-viewed</key>
    <integer>0</integer>
    <key>date-received</key>
    <integer>1328148014</integer>
    <key>flags</key>
    <integer>8590195713</integer>
    <key>gmail-label-ids</key>
    <array>
        <integer>6</integer>
        <integer>2</integer>
    </array>
    <key>remote-id</key>
    <string>204360</string>
</dict>
</plist>
```