
From: LSJ <lsj.island@gmail.com>
Sent: Tuesday, August 28, 2012 1:27 PM
To: Boscoe
Cc: Monique Harry; Jeffrey Epstein
Subject: Re: Early Discoveries

Good Morning
Thank you for up date
Did you get everything ready for shipping?
Thanks
K

Sent from my iPhone

On Aug 28, 2012, at 8:54 AM, Boscoe [REDACTED] > wrote:

> Good Morning
> We have discovered steering linkage damage. There is also more wear than expected on the port edge of the ramp. The. Solution will be a plate eve and plug weldedto the existing plate and frame of the ramp. Quick and strong.... C=aper too...
> More to follow on the steering. U can see evidence of the problem in the=photo of the rudder. It shows a shiny wear spot where there shouldn't be on=

>

> Sent from my iPhone

```
<?xml version=.0" encoding=TF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
    <key>conversation-id</key>
    <integer>228739</integer>
    <key>date-last-viewed</key>
    <integer>0</integer>
    <key>date-received</key>
    <integer>1346160427</integer>
    <key>flags</key>
    <integer>8590195713</integer>
    <key>gmail-label-ids</key>
    <array>
        <integer>6</integer>
        <integer>2</integer>
    </array>
    <key>remote-id</key>
    <string>242750</string>
</dict>
</plist>
```