

---

**From:** Jeffrey Epstein <jeevacation@gmail.com>  
**Sent:** Saturday, November 2, 2013 9:32 PM  
**To:** Eric Roth  
**Cc:** lvjet  
**Subject:** Re: GIV 1085 JE

The jvc is the wrong unit the Bluetooth is operated by android system . App=e needs hardwire . The screen is faulty it is not the adjustments . It is =ld tech , and low quality

On Saturday, November 2, 2013, Eric Roth wrote:

Good evening Jeffrey,<=>

Please read through the attached pdf that identifies where we stand regarding the entertainment system and the air gaspers.

Please do not hesitate to call or email me with any questions you may have.

Additionally, we anticipate going to Teterboro on Thursday morning to work the entertainment system. Would you like to come to the aircraft to hear and see the changes we make that afternoon?</u>

ERIC H. ROTH | PRESIDENT

P 631.737.5900 | C 516.857.6533 | eroth@intljet.com <javascript:\_e({}, 'cxml'=':eroth@intljet.com');>  
<span>| www.intljet.com <http://www.intljet.com/> <http://twitter.com#!/intljet>  
<http://www.facebook.com/intljet>

2221 S=ithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=>

=u>

--

\*\*\*\*\*=\*\*\*\*\*

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com) <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved