

---

**From:** Lvjet <[REDACTED]  
**Sent:** Wednesday, May 7, 2014 10:52 PM  
**To:** jeevacation@gmail.com  
**Cc:** [REDACTED]  
**Subject:** GIV update

Jeffrey,  
Flight time: TEB - STT is 3+13min (+34kt tailwind).

Test flight on GIV today went well,  
-I was pleased with Door seal, inflates fully and db lever is much lower in fwd cockpit area with sound proof material on cabin door.  
-charging dock for stereo remote looks amazing. / Down wash lights above credenza have been replaced./ dish, salt and pepper and several drawers in galley have dividers installed.  
-it was tough to find smooth air during todays flight, I brought Julia=, Mx shop manager, most of flight felt smooth, brief moments our light buffet was present, so I was able to demonstrate to Julian our concerns.,

only issue during flight was cockpit windshield heat regulator failed, part will arrive 9am tomorrow and should be completed by noon= I'm planning to reposition to Teterboro by 3pm for our departure=/div>

let me know if there is a chance you will depart earlier than 6pm?

thank you,  
Larry