
From: Ann Rodriguez <[REDACTED]>
Sent: Tuesday, October 3, 2017 11:01 PM
To: Carlos Rodriguez
Cc: jeffrey E.; Rich Kahn
Subject: PRD: Trim Tabs

Carlos can you please purchase anything needed to fix PRD trim tabs. Once ag=in the trim tabs are not working even after Randy changed the switch. Comin= from St. John today with Mr. Bubbler was very uncomfortable for all

I believe the entire Trim tab system need to be changed:

New Switch (broken inside) -Changed

New Cylinders (might be leaking hydraulic fluid) -not changed New Trim Tabs (might be sticking) -not changed

Thank you,
Ann R.=

.
<?xml version=.0" encoding=TF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>28670</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1507071648</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>6</integer>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>755693</string>
</dict>
</plist>