
From: Larry Visoski [REDACTED]
Sent: Monday, December 1, 2014 6:43 PM
To: Je vacation
Subject: 727

Appears we found the problem, 35° temp sensor, was also the problem of y=u hearing ice pellets traveling through the air ducts on take off,

okay you were right!!

Sent from my iPhone=?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>308252</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1417459392</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>460247</string>
</dict>
</plist>