

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Tuesday, July 24, 2018 10:23 PM  
**To:** Je vacation  
**Cc:** Rich Kahn  
**Subject:** Glv update  
**Attachments:** Untitled attachment 00597.txt; IMG\_2120.PNG; Untitled attachment 00600.txt

Jeffrey

Gulfstream found a chaffing Hydraulic line inside the pylon, Wearing thru during engine removal, this would have been a total loss of Hydraulic fluid on R/H engine.,

Great find!  
(Engine vibration issue??)  
We will see.

Thx  
Larry