

---

**From:** Larry Visoski <████████>  
**Sent:** Tuesday, August 7, 2018 2:06 PM  
**To:** jeffrey E.  
**Subject:** Re: Hydraulic line

Ok,

I will send photos to Kathleen and Rusty asking that question, Since Gulfstream in Palm Beach removed both engines and completed a full Chaffing inspection of the pylon and all lines looking for this exact line that was rubbing

Sent from my iPhone

On=Aug 7, 2018, at 9:29 AM, jeffrey E. <jeevacation@gmail.com <mailto:jeevacation@gmail.com>> wrote:

i want to know what was missed an why = the ride is entierly differtn with the new engines

On Tue, Aug 7, 2018 at 9:27 AM, Larry <Jeffrey  
Below are photos of the Hydraulic line,,  
Left Engine Pylon,

This is L/H pylon, the freshly painted lime green line is the new Hydraulic line installed,

\*\*\*the chaffing was behind the silver heat duct in this photo,,

Sent from my iPhone  
<mailto:████████>

--

<div class="m\_-7216834186086578951gmail\_signature" data-smartmail="gmail\_signature">

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com) <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

[jeevacation@gmail.com](mailto:jeevacation@gmail.com), and  
destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

=