
From: jeffrey E. <jeevacation@gmail.com>
Sent: Wednesday, July 11, 2018 10:56 PM
To: Larry Visoski
Subject: Re: G550 engine

yes

On Wed, Jul 11, 2018 at 6:40 PM, Larry Visoski <[REDACTED]> <mailto:[REDACTED]> > wrote:

Jeffrey

While updating the Data bases on G550, Pete noticed a

"L Engine Maintenance" code on the panel,

He downloaded the information from the aircraft and sent to Rolls Royce for evaluation,

We have this code before During flight, but it clears before landing.,

Rolls Royce recommends changing the EEC

"electronic engine control"

Small computer located on top of the engine,,

Part has arrived this evening and will be installed by Gulfstream at JeT aviation Teterboro, should be ready to run Engines by 1 PM tomorrow, I will be on location as well

This part is covered under Rolls Royce Corporate care

Is this ok?

Thx

Larry

Sent from my iPhone

--

=A0 please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to <mailto:jeevacation@gmail.com> target="_blank">jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--000000000000195f3c0570c126c8-- conversation-id 311948 date-last-viewed 0 date-received 1531349753 flags
8590195713 gmail-label-ids 7 remote-id 835955