
From: jeffrey E. <jeevacation@gmail.com>
Sent: Tuesday, August 7, 2018 1:12 PM
To: Larry Visoski
Subject: Re: Hydraulic line

why would the vibration be any less. on descent. ?=C2 we had talked about constant pressure.?

On Tue, Aug 7, 2018 at 9:04 AM, Larr= Visoski <lvjet@aol.com <mailto:lvjet@aol.com> > wrote:

Jeffrey
Below are photos of the Hydraulic line,,
Left Engine Pylon,

This is L/H pylon, the freshly painted lime green line is the new Hydraulic=line installed,
***the chaffing was behind the silver heat duct in this photo,,

Sent from my iPhone

--
=div class="gmail_signature" data-smartmail="gmail_signature">
please note

The=information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE U=authorized use, disclosure or copying of this communication or any part=thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return=e-mail or by e-mail to

jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--00000000000006e95a90572d8225a-- conversation-id 314055 date-last-viewed 0 date-received 1533647499 flags 8590195713 gmail-label-ids 6 7 remote-id 842660