
From: Richard Kahn <[REDACTED]>
Sent: Tuesday, January 8, 2019 11:56 PM
To: Jeffrey Epstein
Subject: Fwd: LSJ

Richard Kahn
HBRK Associates =nc.
575 Lexington =venue, 4th Floor
New York, NY =0022
tel = [REDACTED]
fax = [REDACTED]
cell = [REDACTED]

Begin forwarded message:

From: =/b>[REDACTED]>

Subject: =/b>LSJ

Date: =/b>January 8, 2019 at 3:43:33 PM =ST

To: =/b>"Richard Kahn" [REDACTED]>

Richard:

Photo 9039 is a leak originating from one of the two PX units =n the skid. This leak has been there since before Gemini =ot involved. We wanted to complete all the other =pgrades to the unit before taking this one on.

Photo 9040 is a leak from the new cartridge filter housing. =nbsp;We reported this at the time of commissioning. =nbsp;We filed a warranty claim with the manufacturer on =ehalf of LSJ but they were late in getting the new seal sent to us. We had planned on changing this seal when =e were last on island but the seal showed up a week =ater. We will be addressing this leak when we =eturn to install the new intake pump station the week of January 21st.

Do you have any =pdate on the status of the new fiber optic cable? This needs to be in place and terminated before we get there to =ermit the control system to be finalized.

Dean

-----Original message-----

From: Richard Kahn <[REDACTED]>

Sent: Tuesday, January 8, 2019 12:23 PM

To: [REDACTED]

Subject: <br class="">

Good afternoon. I visited LSJ yesterday and noticed a few spots with water leaking. Can you please explain so I can understand better. Thank you.

=