

---

**From:** Eric Roth [REDACTED]  
**Sent:** Monday, November 19, 2018 3:34 PM  
**To:** J  
**Cc:** [REDACTED]  
**Subject:** FW: Plan D, LLC "open items"

Best Regards,

Eric

ERIC H. ROTH<=> | PRESIDENT

P</=pan> [REDACTED] [www.intljet.com](http://www.intljet.com)  
<<http://www.intljet.com/>> <<http://twitter.com/#!/intljet>> <<http://www.facebook.com/intljet>>

-----  
2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=:p>

From: Eric Roth  
Sent: Monday, November 19, 2018 10:30 AM  
To: Jay Massar <[REDACTED]>  
Cc: Eric Roth [REDACTED]  
Subject: Plan D, LLC "open items"

Good morning Jeffrey,

In order to properly schedule and for everyone to be on the same page, below is the consolidated list of items that we have discussed. Please read through this carefully and add whatever you want completed to this list. Certain items may need to be expounded, so we would appreciate any and all words you could contribute to our understanding.

Once we have this list solidified, we can then discuss schedule and down time.

As always, please do not hesitate to call with any questions you may have.

Lastly, I have included the link to your 3D walkthrough to refresh your memory (as well as ours).

Thank you.

<https://my.matterport.com/show/?m=2nLwZFNAHp4> <<https://my.matterport.com/show/?m=2nLwZFNAHp4>> =/p>

Fwd L/H Bulkhead Monitor Closeout= /o:p>

Fabricate wood handle and finish to replace existing clear vinyl tab

Fwd R/H Cabin Bulkhead

Fabricate temporary cover for Exit Sign in wood veneer to complement existing

Fwd Cabin Pocket Door

Camouflage door handle and create visual symmetry of seam(s). Fabricate rectangle veneer with top of piece at same elevation as top of L/H bulkhead monitor opening. Lower horizontal line could be at top of seat back height. Overall width approx. 5.0"

#### Mid Cabin Curtain

Fabricate new one? Sew vertical seams in existing to help minimize the wrinkles at the bottom? Need additional retaining strip with metal plated snaps.

#### Monitor on Ledge

New monitor (in the color black) with wing arm mounted to ledge?

#### Speaker Bar

Mounted above side duct outboard of lower side panel? Incorporate speaker grill to allow acoustic transmissivity?

#### Sub-Woofer

What are we doing with Carry On sub-woofer?

#### Divan Arm rests

Add (.50" ?) foam to inboard vertical and top of arms (to be "softer")

#### Divan "Carry On" mattress

Reupholster in new fabric (Crate & Barrel fabric?)

#### Aft Galley / Lavatory door

Replace double stick tape with contact adhesive on wood veneer closeout for horizontal piece.

#### Aft R/H Galley

Replace double stick tape with contact adhesive on wood veneer closeout for aft bulkhead piece.

#### Aft Lavatory Potty Seat

Cut and sew white fabric pad in half

Aft Lavatory Toilet Paper Door

Work "garage door" so that it is more stable when being open or closed

Aft L/H Galley

Replace existing LED lights with new both inside the glass rack compartment and underneath that illuminates the countertop.

Aft Galley

Fabricate inserts to contain customer supplied carry on items.

Foot Stool

Fabricate a second foot stool (covered in carpet to match the existing) so that they both fit into the existing "bag dock" on the L/H mid cabin

Sidewall Table Pulls

Hard edges are uncomfortable against fingers. Cover edge in leather / rubber / trim this piece for comfort


Aft Lavatory Door

"Hinge" on door makes noise

Best Regards,

Eric

ERIC H. ROTH<=> | PRESIDENT

 www.intljet.=om  
<http://www.intljet.com/> <http://twitter.com/#!/intljet> <http://www.facebook.com/intljet>

-----

2221 S=ithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=:p>