
From: Kyle reavis <[REDACTED]>
Sent: Friday, October 19, 2018 2:05 PM
To: jeffrey E.
Cc: Richard Kahn
Subject: Re: Generator building Rust

No sir, not that door, one of the attachments didnt get in=luded there. That door has been 100% rusted out, that one has much m=re than a spot.

On Fr=, Oct 19, 2018 at 6:45 AM J <j=evacation@gmail.com <mailto:jeevacation@gmail.com>> wrote:

did you just descibe that door as having a rust "spo="

On =ri, Oct 19, 2018 at 8:58 AM Kyle reavis <[REDACTED] <mailto:kyleusvi@gmail.com>> wrote:

Mr Epstein,

The doors and door hardware all have rust spots.=C2◆ Vents have rust along with the leavouts for the new exhaust vents.=C2◆

Kyle
<=div>

--

please note

The information contained in this communication is confidential, may b= attorney-client privileged, may constitute inside information, and is =ntended only for the use of the addressee. It is the property of JEE=br>Unauthorized use, disclosure or copying of this communication or any=part thereof is strictly prohibited and may be unlawful. If you have re=eived this communication in error, please notify us immediately by r=turn e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication a=d all copies thereof, including all attachments. copyright -all rights =eserved