
From: jeffrey E. <jeevacation@gmail.com>
Sent: Thursday, September 14, 2017 12:28 PM
To: Eric Roth; Ivjet

we forgot to discuss back bulkhead and lav door =C2 , also lumbar adjustments in seats. need review

1. priorities. color of wood? seat spacers. =A0 psu;s lav- galley rattles. tables. psu, =rawers latches. do we add pieces to foot rests to make t=em usefull or at least adjust so they are horizontal on deployment.=C2 . do we remove stair covering. so gulf=tream can paint? thoughts?

-- =br>
please note

=he information contained in this communication is confidential, may be =ttorney-client privileged, may constitute inside information, and is in=ended only for the use of the addressee. It is the property of JEEUnauthorized use, disclosure or copying of this communication or any p=rt thereof is strictly prohibited and may be unlawful. If you have rece=ved this communication in error, please notify us immediately by ret=rn e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication an= all copies thereof, including all attachments. copyright -all rights r=served

--94eb2c11e478cabce70559256958-- conversation-id 31265 date-last-viewed 0 date-received 1505392107 flags 8590195713 gmail-label-ids 7 remote-id 749755