

---

**From:** Richard Kahn [REDACTED]  
**Sent:** Friday, September 28, 2018 6:57 PM  
**To:** Jeffrey Epstein  
**Subject:** PBI - Water on main entry door

carluz noticed leak today that is coming from master tub plumber just told me it is from deck filler valve need scaffolding to access which they hope to have later =oday or tomorrow repairs should all be completed =y middle of next week hope paris trip is still on =or sunday..

Richard Kahn  
HBRK Associates Inc.  
575 =exington Avenue 4th Floor  
New York, NY 10022  
tel [REDACTED]  
fax [REDACTED]  
cel [REDACTED]

Begin forwarded message:

From: CARLUZ TOYLO [REDACTED] >  
Subject: Re: Tub leaks  
Date: September 28, 2018 at 2:45:16 PM EDT  
To: Richard Kahn [REDACTED]

Above main entry, this is what it looks right =ow. Water is shut off , thanks

Carluz & =rline Toylo  
358 EL Brillo Way

Begin forwarded message:

From: CARLUZ TOYLO <[REDACTED]>

Subject: Tub Water leaks

Date: September 28, 2018 at 10:34:35 AM EDT

To: Richard Kahn <[REDACTED]>

Cc: Renato Lacson <[REDACTED]> >, Bella Klein <[REDACTED]>

Suspected water leaks these 3 source of connection.

Trace of water in hose could be at the bottom connection. Below previous photo was the water marks .

Carluz & Arline Toylo  
358 EL Mirillo Way  
Palm Beach , FL 33480

Begin forwarded message:

From: CARLUZ TOYLO <[REDACTED]>

Subject: Water on main entry door

Date: September 28, 2018 at 10:19:00 AM EDT

To: Richard Kahn <[REDACTED]>

Hi Rich ,

FYI - Just found out this water marks on the ceiling , above the bath tub of Masters Bedroom. I am trying to locate exact area where trace of water drip . Thank you

In the main time We turn off water on this room 'til further inspection from plumber

Carluz & Arline Toylo  
358 EL Arillo Way  
Palm Beach , FL 33480

=