
From: Larry Visoski [REDACTED]
Sent: Saturday, September 15, 2018 12:44 PM
To: jeffrey E.
Subject: Re:

Thx,, Wheels up 5pm confirmed to PBI,,,

The captains Display Tube DU1 was Blank.

</=iv>

It's a HAPP covered item,

Op=ion 1 exchange the part,

However, there is no availability for ex=hange since we have the older style DU tube, and Honeywell is not supportin= this tube and supply is low for parts, (we exchanged DU3 i= Nov while in Savannah)

30 Day turn time for repair.,

<=iv> is Unacceptable

Option 2 is what we are t=ying to do,

Upgrade to HAPP extended coverage which is \$18k per y=ar additional.

Will allow us access to the New Upgraded DU T=bes that "should" be available,,

O=tion 3

Outright purchase of an "As Removed" DU Tu=e \$80k

The listed value of each DU Tubes is \$175k<=div>

S=nt from my iPhone

On Sep 15, 2018, at 6:54 AM, jeffrey E. <=jeevacation@gmail.com <mailto:jeevacation@gmail.com> > wrot=:

5 pm wheels u=. dont know if you want to visit the 550 today?

--

jeevacation@gmail.com, and
destroy this communication and al= copies thereof,
including all attachments. copyright -all rights reserv=d

=