

---

**From:** Larry Visoski <[REDACTED]  
**Sent:** Tuesday, January 15, 2019 2:08 AM  
**To:** Je vacation  
**Cc:** Rich Kahn  
**Subject:** GIV corrosion  
**Attachments:** IMG\_3879.JPG; Untitled attachment 00209.txt; IMG\_3880.JPG; Untitled attachment 00212.txt; IMG\_3881.JPG; Untitled attachment 00215.txt

Jeffrey

While Gulfstream was repairing a broken wire for the Thrust Reverser, they noticed some corrosion in the pylon area. (Photos below) They released the aircraft, return to service today. Accept, I have to sign a disclaimer noting the corrosion.

I have requested a formal quote for the repair, and will fwd once I receive it.

Thx  
Larry