
From: [REDACTED]
Sent: Monday, January 28, 2019 1:58 PM
To: Richard Kahn
Cc: jeevacation@gmail.com
Subject: Re: ZM MB S500 Windshield

Thank you
I will reach out today <=r>

Sent from my iPhone

<=iv dir="ltr">

On Jan 26, 2019, at 3:35 PM, Richard Kahn <770=11 th Ave Btw 53rd St & 54th St New York, NY 10019 <x-apple-data-detectors://1>

T=l: ([REDACTED] Fax: [REDACTED] [REDACTED]<mailto:[REDACTED]<http://www.mbmmanhattan.com/>

Richard Kahn
HBRK Associates Inc.
575 Lexington Avenue, 4th Floor
New York, NY 10022
Tel [REDACTED]
Fax [REDACTED]
Cell [REDACTED]

On Jan 22, 2019, at 3:30 PM, [REDACTED].com> wrote:

Good afternoon Unfortunately the aftermarket windshield ordered for the 2002 Mercedes S500 Guard Car did not workout

It appears the Original Windshield which has two layers of glass was installed from the inside.

I contacted Mercedes Benz of Denver, but they were unable to provide fix for this problem

The aftermarket shield has been returned at no cost to you

Rich do you have a contact in NYC that could assist us?

Please advise

Regards [REDACTED]

Sent from my iPhone

=