

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Wednesday, August 29, 2018 4:33 PM  
**To:** Eric Roth  
**Subject:** Re: sub woofer

no

On Wed, Aug 29, 2018 at 12:32 PM, Eric Roth <[REDACTED] <mailto:[REDACTED]>> wrote:

Jeffrey,

Maurice had a better idea for the subwoofer.

Right now, the tray that holds your subwoofer sits about .50" or so above the carpet. If we increase the gap between the bottom of the tray and the carpet another 1.5", we could install the subwoofer close to its original position in the aircraft (as originally designed). This would leave a 2.00" space under the tray vs .50".

Personally, I believe this is a better idea.

Your thoughts?....

Best Regards,

Eric

ERIC H. ROTH<=> | PRESIDENT

P</=pan> [REDACTED] | C=/b> [REDACTED] mailto:[REDACTED]> |  
www.intljet.com <http://www.intljet.com/> <http://twitter.com/#!/intljet> [REDACTED]

-----

2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779

--

=A0 please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved