

**From:** [REDACTED]  
**Sent:** Tuesday, January 22, 2019 8:31 PM  
**To:** jeevacation@gmail.com  
**Cc:** Richard Kahn [REDACTED]  
**Subject:** ZM MB S500 Windshield

Good afternoon

Unfortunately the aftermarket windshield ordered for the 2002 Mercedes S500 G=ard Car did not workout It appears the Original Windshield which has two layers of glass was install=d from the inside.

I contacted Mercedes Benz of Denver, but they where unable to provide fix fo= this problem The aftermarket shield has been returned at no cost to you Rich do you have a contact in NYC that could assist us?

Please advise

Regards Brice

Sent from my iPhone=?xml version=.0" encoding=TF-8"?>  
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">  
<plist version=.0">  
<dict>  
    <key>conversation-id</key>  
    <integer>331076</integer>  
    <key>date-last-viewed</key>  
    <integer>0</integer>  
    <key>date-received</key>  
    <integer>1548189058</integer>  
    <key>flags</key>  
    <integer>8590195713</integer>  
    <key>gmail-label-ids</key>  
    <array>  
        <integer>2</integer>  
        <integer>6</integer>  
    </array>  
    <key>remote-id</key>  
    <string>893148</string>  
</dict>  
</plist>