
From: Richard Kahn <[REDACTED]>
Sent: Tuesday, January 22, 2019 8:01 PM
To: Jeffrey Epstein
Subject: Fwd: GSJ New Generator

Richard Kahn
HBRK Associates Inc.
575 Lexington Avenue 4th Floor
New York, NY 10022
tel [REDACTED]
fax [REDACTED]
cell [REDACTED]

Begin forwarded message:

From: =/b>michael glidden <[REDACTED]>
Subject: =/b>Re: GSJ New =enerator
Date: =/b>January 22, 2019 at 2:36:39 PM =ST
To: =/b>Richard Kahn <[REDACTED]>
Cc: [REDACTED] <mailto:[REDACTED]>

All fluids were checked at startup and first oil change was =oing to be next week when I got back.

Sent from my iPhone

On =an 22, 2019, at 10:27 AM, Richard Kahn <[REDACTED]> wrote:

please advise if oil was ever changed or =dded when GSJ was installed
thank you

Richard Kahn
HBRK Associates Inc.

575 Lexington Avenue 4th Floor

New York, NY 10022

tel [REDACTED]

fax [REDACTED]

cell [REDACTED]

Begin forwarded message:

From: Ann Rodriguez <[REDACTED]>

Subject: GSJ New Generator

Date: January 22, 2019 at 12:35:56 PM EST

To: Rich Kahn <[REDACTED]>, Daphne Wallace <[REDACTED]>

Cc: Jeffrey Epstein <jeevacation@gmail.com <mailto:jeevacation@gmail.com>>

Hi Rich & Daph,

I got back to GSJ at 12:45pm.

I asked Tap why is the generator so loud? if it's new? He went to check it for me and said it doesn't have any oil in it.

I asked him to please put oil in it. Tap said that he have to shut it down right now. This is Bad

One of Elderfield workers said that the carpenter on the each (Brian) is the one that checks on it during the day

Pic 1: first oil test

Pic 2: second oil test

Pic 3: oil check during Shutoff

<image2.jpeg>

<image3.jpeg>

<image4.jpeg>

<image1.jpeg>

Sent from my Phone

=