

---

**From:** Richard Kahn <[REDACTED]>  
**Sent:** Friday, March 8, 2019 8:08 PM  
**To:** Stephanie Remington  
**Cc:** Daphne Wallace; michael glidden  
**Subject:** Re: Luis

are =ll those pictures from the master?  
what about cabanas =nd library?  
please advise  
thanks

Richard Kahn  
HBRK Associates Inc.  
575 Lexington Avenue 4th Floor  
New York, NY 10022  
tel [REDACTED]  
fax [REDACTED]  
cell [REDACTED]

On Mar 8, 2019, at 2:52 PM, Stephanie Remington <sremington.sjg@gmail.com> wrote:

Luis was here for a bit this morning. He looked =t all the floors and took notes on what phase each one was in. He said =e would be in touch with you, Rich.

The scratch =n the master is visible and not in a place that can be easily covered. = can't imagine JE wouldn't want it repaired, but to do =o will involve stripping the master back down and sanding, then putting =ll the coats back on.

Also, I asked him about =iscoloration around the edges. He said it was from condensation in the =alls. He said the only thing that can really be done is that they can =o around the edges with a fine line of a matching paint they have that =lends with the floor which would be recommended unless we're =lanning to add trim or quarter round.

See =ttached photos of discoloration and scratch.

<IMG\_7404.jpg>

<IMG\_7408.jpeg>

On Fri, Mar 8, 2019 at 3:15 PM Richard Kahn <richardkahn12@gmail.com> wrote:

how did visit go?  
can you please provide an update

thanks

Richard Kahn  
HBRK Associates Inc.  
575 Lexington Avenue 4th Floor  
New York, NY 10022  
tel 212-971-1306  
fax 212-320-0381  
cell 917-414-7584

--

Stephanie Remington  
LSJE, =LC

=