

---

**From:** Richard Kahn <[REDACTED]  
**Sent:** Tuesday, March 12, 2019 8:00 PM  
**To:** Jeffrey Epstein  
**Subject:** Steel building

not =hat i am aware of..  
problem is that if i do not push =everyone daily nothing gets done..  
unfortunately =ately i have been busy with banks, brokerages and hedge =unds..

last =mails to glidden below..

Richard Kahn  
HBRK Associates Inc.  
575 Lexington Avenue 4th Floor  
New York, NY 10022  
tel [REDACTED]  
fax [REDACTED]  
cell [REDACTED]

On Mar 12, 2019, at 3:57 PM, J <jeevacation@gmail.com> wrote:

Did we order the building steel

--

=nbsp;

Begin =orwarded message:

From: Richard Kahn <[REDACTED]  
Subject: Fwd: 40x60 bldg.

Date: March 7, 2019 at 4:15:25 PM EST

To: michael glidden <[REDACTED]

Cc: Daphne Wallace

>, Stephanie Remington

i =m not sure if you responded and i apologize if you did and i missed =t..  
could you please update on status and next steps as =ee would like ordered asap  
thank you

Richard Kahn  
HBRK =ssociates Inc.  
575 Lexington Avenue 4th =loor  
New York, NY 10022  
tel [REDACTED]  
fax [REDACTED]  
cell [REDACTED]

Begin =orwarded message:

From: Richard Kahn <richardkahn12@gmail.com>

Subject: Fwd: 40x60 bldg.

Date: February 22, 2019 at 3:25:25 PM EST

To: michael glidden <[REDACTED]>

Cc: Daphne Wallace <[REDACTED]>, Stephanie Remington <[REDACTED]>

can you please review and reply ASAP  
thanks

Richard Kahn  
HBRK Associates Inc.  
575 Lexington Avenue 4th Floor  
New York, =Y 10022  
tel [REDACTED]  
fax [REDACTED]  
cell [REDACTED]

Begin forwarded message:

From: Brian Buck <[REDACTED]>

Subject: RE: 40x60 bldg.

Date: February 21, 2019 at 1:30:57 PM EST

To: michael glidden <[REDACTED]>

Cc: Daphne Wallace <[REDACTED]>, Richard Kahn <[REDACTED]>

Stephanie Remington <[REDACTED]>

Michael,

I want to put together a drawing for you but I need to clarify a couple of things first.

\* So the building was not erected according to plans, it was modified somewhat in =he field? The building was a fully sheeted building. So the =rector opened up the left end wall to 8'2" and the back =ide wall to 10'6" but was sheeted 5'6" =east the roof of the 14" slab. How deep is the retaining =all?

\* Are the (2) 12' x 14' =oors on the marked up dwg you sent back (front side wall and right end =all) to be included in these locations? Are we adding a third =ollup door in bay #3 of the front side wall where you currently have a =5' rough opening?

Assuming the above is correct this is =hat I would propose.

We previously had the left end wall as = flush girt condition. I would change it to a bypass girt so that =he girt would extend 10"(depth of girt) past the face of the =olumn. This way a) the panel would lap over the retaining wall(if it is =0" or less deep) for a good seal and b) would allow us to shift =he columns in 10". This will clear the existing anchor =olts which will be cut off and providing the pier is sufficient in =idth, would save a whole lot of time and labor on those (4) left end =all columns.

I'd leave the back side wall =pen to 10'6", sheet above the roof and provide a wall =o roof flashing. I'm assuming the slab is all even =elevation?

I think if we change the bay spacings =lightly(less than a foot in most cases) we can avoid having to do a lot =f the demolition.

What do you think?

Regards,  
Brian Buck  
President

Direct [REDACTED]  
Toll Free [REDACTED]

6855 Lyons Technology Circle | Suite 18 | Coconut Creek FL 33073  
1107 Battlewood Street | Suite 221 | Franklin TN 37069

Legal Disclaimer: This communication and any attachments contain information which is confidential and may also be privileged. It is for the exclusive use of the intended recipient(s). If you are not the intended recipient(s) please note that any form of disclosure, distribution, copying or use of this communication or the information in it or in any attachments is strictly prohibited and may be unlawful. Where the content of this email is personal or otherwise unconnected with the firm's or its clients' business, Buck Steel accepts no responsibility or liability for such content. E-mail communications cannot be guaranteed to be secure or error free, as information could be intercepted, corrupted, amended, lost, destroyed, arrive late or incomplete, or contain viruses. We do not accept liability for any such matters or their consequences.

From: michael glidden <[REDACTED]>  
Sent: Wednesday, February 20, 2019 4:56 PM  
To: Brian Buck <[REDACTED]>  
Cc: Daphne Wallace <[REDACTED]>; Richard Kahn <[REDACTED]>  
Stephanie Remington <[REDACTED]>  
Subject: Fwd: 40x60 bldg.

Good afternoon Brian.  
I thought that this might help understanding how the building was installed. The only openings  
are as marked up.  
I will gather the information tomorrow that we discussed.

Begin forwarded message:

From: michael glidden <[REDACTED]>  
Subject: 40x60 bldg.  
Date: February 20, 2019 at 4:47:48 PM AST  
To: mjg.lsj@gmail.com

Sent from my Phone

=/div>

