

---

**From:** Stephanie Remington [REDACTED]  
**Sent:** Sunday, March 10, 2019 12:33 PM  
**To:** J  
**Subject:** Re: Mold inside master ductwork

The old ductwork in the master bedroom was full of mold and removed. Reefco is now preparing to do the same thing to the Master-bath side.

=old means moisture. The environment here is humid. The cold indoors against the hot outdoors makes everything in between sweat - ductwork, stone wall, etc. We even see the moisture around the edges of the floor.  
=div dir="auto">

Let me talk to Mike about possibilities for moving air and/or wicking moisture in the attic - attic fans= desiccant, DamRid, special lighting, etc. Will do some research and get back to you.

On Sun, Mar 10, 2019 at 8:15 AM J <jeevacation@gmail.com> wrote:

this says the ducts in the master are being removed. !! what happened

On Mon, Feb 25, 2019 at 2:21 PM michael glidden [REDACTED] <mailto:[REDACTED]> wrote:

The light gray section is the normal color.

All the duct in the bath is now being removed also. The bath and the bedroom are separate systems.

Sent from my iPhone

--

=C2 please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this

return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com>, and destroy this communication and all copies hereof, including all attachments. copyright -all rights reserved </iv>

--

Stephanie Remington