
From: J <jeevacation@gmail.com>
Sent: Thursday, February 21, 2019 1:50 AM
To: Larry Visoski
Subject: Re: G550

Ok

On Wed, Feb 20, 2019 at 8:29 PM Larry V=soski <[REDACTED]> wrote:

Jeffrey

We are having Gulsream troubleshooting a R/H Engine fault code, ref the EE= (Electronic Engine control), makes mention of channel A and B source info=mation code, that came on when i repositioned the plane from USCusto=s to Atlantic ramp,

Rolls Royce is evaluating the computer download for the engine, could be a =imple replacement of the EEC located on the engine ,,

Just heads up,

,I'll keep you posted ,, shouldn't be a difficult repair, <=r>

Thx

Larry

Sent from my iPhone

--

=A0 please note

The information contained in this=communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the=addressee. It is the property of JEE Unauthorized use, disclosure or=copying of this communication or any part thereof is strictly prohibite= and may be unlawful. If you have received this communication in err=r, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com<=a>, and destroy this communication and all copies thereof, including=all attachments. copyright -all rights reserved

--000000000000683c9405825db2d4-- conversation-id 336912 date-last-viewed 0 date-received 1550713820 flags 8590195713 remote-id 901679