
From: Larry Visoski <[REDACTED]>
Sent: Thursday, February 21, 2019 1:30 AM
To: Jeffrey
Subject: G550

Jeffrey

We are having Gulfstream troubleshooting a R/H Engine fault code, ref the EEC=(Electronic Engine control), makes mention of channel A and B source information code, that came on when i repositioned the plane from USCustoms to At=antic ramp, Rolls Royce is evaluating the computer download for the engine, could be a simple replacement of the EEC located on the engine , Just heads up, ,I'll keep you posted , shouldn't be a difficult repair, = Thx Larry

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>336912</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1550712586</integer>
 <key>flags</key>
 <integer>8590195717</integer>
 <key>remote-id</key>
 <string>901677</string>
</dict>
</plist>