

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Sunday, September 3, 2017 2:22 PM  
**To:** Jay Massar  
**Subject:** Fwd:

----- Forwarded message -----

From: jeffrey E. <jeeva=ation@gmail.com <mailto:jeevacation@gmail.com>>  
Date: Sat, Sep 2, 2017 at 10:25 PM  
Subject: =e:  
To: Eric Roth <[REDACTED]> &=t;

Great

On Sat, Sep 2, 2017 at 9:41 PM Eric Roth &=t; [REDACTED] /a>> wrote:  
<mailto:[REDACTED]>

Will review with Larry and then at some point with yourself.

<=r>

<=r> Best regards,

Eric

Eric H. Roth, President  
International Jet Interiors

[REDACTED]  
www.intljet.com</> <http://www.intljet.com>

On Sep 2, 2017, at 3:32 PM, jeffrey E. <jeevacation@gmail.com <mailto:jeevacation@gmail.com>> wrote:

90 percent right. most work really great some ,unfor=unatley mostly my fault - bad. some ,(divan ) oth=rs just overlooked . fyi it appears temp fan in b=ck got disconnectd , hot in cabin over the atlantic , not muc= fun. but .. it happens\

1

1. the sides of the cabin door in front are two different colors. ?=C2 very ugly

2 iphone charger not good for flying. not solid. .

3 I suggest we inset leather on drink rails. cover cup holders=and make them smaller. for voss. and find magnetic charger so phone

4. my captain chair needs a side pouch low hidden for glasses and pens. we might make the arms wider on just this chair

5. footrests. need adjustment , they are currently useless. =A0 we should make a small ottoman \

6. prontos work well and should be installed in place of small screen= behind the panels on the window line\

7 the table mechanism needs to be re cut. magnets taken out. =A0 and stiffened where it meets the vertical panel. which had = lot of rattles larry has video

8 . I think we should put a stictch on the tops. they look a little like placemats. without

9 the captains chair needs a repad.

10 the chairs in the cabin were shaking quite a bit on take off

11. the psu in the galley which looks great shold be changed to white and m=re down wash lights installed.

12 credenz top should be white to match the galley, and seats like the g4

13, we should cover aft bulkhead and lav door with fabric

14 many of the doors and latches were rattling

15. shelf for food storage with proper size top opening bag\

16. over the baggae door we left the old leather , change to white.

17. the psu over the sink should be white and cut back and made shorter, =A0 I kept banging my head when brushing my teeth

18 some type of cover for toilet paper

19. more cushion on potty seat. PLENTY of room

20 new potty seat. not nice

21 rear mag rack, should be covered as well in fabric

22. bag carrier should have higher sides to lay down books

23 . lets recover the two front seats in fabric

24. biggest is the DIVAN . almost nothing right. . arms should be higher and either fabric and soft to lean on , they should extend if possible to the out board wall. the fabric and welting= does not look good. . on the seat cushion , it is=deformed, I took photos.? the rear cushions are much too hard. angled incorrectly and the welting was put on the front side instead of the back. =A0 you and i were worried about the corner when you sat back on them= . when made into a bed, the drink rail is e=posed , and rough we need to rethink the whole .

25. there is a light on in the bathroom floor that i cant turn off.

26 some of the switches need to be changed they are old and rattle. same for some latches

27 the new wool covered glassware covered rattled like crazy on take off. . putty on the sides of the outboard?\

28 it is going to be great. . the divan arms look too bulky and hard maybe cashmere arms with foam.  
not sure

29 odd -but some chair cushions are different than others. i measured. ? i kept switching them around

lots of photos and some videos

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com) <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--

=AO please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com) <<mailto:jeevacation@gmail.com>> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--

=C2 please note

The information contained in this communication is confidential, may be attorney-client privileged, and may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure, or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and destroy this communication and all copies thereof, including all attachments. Copyright - all rights reserved

--94eb2c042b46722262055849b75c-- conversation-id 32898 date-last-viewed 0 date-received 1504448516 flags 8590195713 gmail-label-ids 7 remote-id 746360