
From: Cashkim Bussue [REDACTED]
Sent: Wednesday, April 3, 2019 7:53 PM
To: jeevacation@gmail.com
Cc: [REDACTED]
Attachments: IMG_6920.JPG; Untitled attachment 00848.txt; IMG_6921.JPG; Untitled attachment 00851.txt; IMG_6922.JPG; Untitled attachment 00854.txt; IMG_6923.JPG; Untitled attachment 00857.txt; IMG_6924.JPG; Untitled attachment 00860.txt; IMG_6941.JPG; Untitled attachment 00863.txt; IMG_6942.JPG; Untitled attachment 00866.txt; IMG_6943.JPG; Untitled attachment 00869.txt

Attached are images coming from inside the oil Room with cracks on the floor=which I presume is the reason for the leakage inside the Fuel tank.