

---

**From:** Larry Visoski <████████>  
**Sent:** Monday, September 4, 2017 1:12 PM  
**To:** Je vacation  
**Subject:** G550 update

Jeffrey

Gulfstream Tech o=s Savannah was perfect with their trouble shooting!

Our R/H Low Li=it Valve is leaking warm air due to deterioration of the Butterfly valve se=il.

Right Hand valve is the worst,, the Left is leaking a li=tle., I'll change them both.

To determine if the seal is go=d, You hold a flashlight at one end of the valve and no light should be see= coming through, see photo below:

This is wh=et Gulfstream sent for troubleshooting, which is exactly our issue.

From Tech Ops;

First, above Locating low limit valves at thi= time, HF coupler arrives in London tonight, will ship all parts from Londo= once they are located. <x-apple-data-detectors:/=1>

\*\*\*Best case scenario, we should have pa=ts in hand Wednesday,

Thx,  
Larry

<=iv>

Sent from my iPhone

=