
From: Larry Visoski <[REDACTED]>
Sent: Friday, August 25, 2017 4:09 PM
To: Je vacation
Subject: G550 Photos
Attachments: IMG_0742.JPG; Untitled attachment 00607.txt; IMG_0744.JPG; Untitled attachment 00610.txt; IMG_0743.JPG; Untitled attachment 00613.txt; IMG_0746.JPG; Untitled attachment 00616.txt; IMG_0748.JPG; Untitled attachment 00619.txt; IMG_0747.JPG; Untitled attachment 00622.txt; IMG_0749.JPG; Untitled attachment 00625.txt; IMG_0745.JPG; Untitled attachment 00628.txt

Jeffrey

Pete sent more photos today.,

1-Pete noticed we have a CAS message, "EVS Maintenance" appeared on displays=today, Pete spoke with Gulfstream Tech support, appears to be a fault in EV= Widow camera controller.,

Exchange Priced \$6500,. Part will arrive Monday, Pete will install,. Small b=x behind Capt seat.

2-Jay had to send the R/H Fwd

Cabin window shade for repair,. It would not open or Close, should be back T=esday next week, All shades worked fine when we arrived, I'll make sure to i=spect and functionally check all interior lights, shades, stereo etc next w=ek.

Coincidence? I'm thankful Eric is not doing any major alteration, We flew=the G550 on 16 trips, with NO issues.,