
From: jeffrey E. <jeevacation@gmail.com>
Sent: Friday, August 25, 2017 4:12 PM
To: Larry Visoski; Eric Roth
Subject: Re: G550 Photos

we decided no lock needed why is there a hole ? and =atch

On=Fri, Aug 25, 2017 at 12:09 PM, Larry Visoski <████████> wr=te:

Jeffrey
Pete sent more photos today,.

1-Pete noticed we have a CAS message, "EVS Maintenance" appeared =n displays today, Pete spoke with Gulfstream Tech support, appears to be a=fault in EVS Widow camera controller,.

Exchange Priced \$6500,. Part will arrive Monday, Pete will install,. Small =ox behind Capt seat.

2-Jay had to send the R/H Fwd

Cabin window shade for repair,. It would not open or Close, should be back =uesday next week, All shades worked fine when we arrived, I'll make su=e to inspect and functionally check all interior lights, shades, stereo et= next week.

Coincidence? I'm thankful Eric is not doing any major alter=tion, We flew the G550 on 16 trips, with NO issues,.

Sent from my iPad

--

conversation-id 34328 date-last-viewed 0 date-received 1503677528 flags 8590195713 gmail-label-ids 7 remote-id 743503