

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Tuesday, April 25, 2017 4:48 PM  
**To:** Richard Kahn  
**Subject:** Re: LSJ Staff Cottage AC units

replace

On Tue, Apr 25, 2017 at 12:22 PM, Richard Kahn <[REDACTED]> <[REDACTED]> > wrote:

brice email with photos and cost to=replace all 3 units totaling 14,124.50  
please advise if we should keep=and clean, replace or only replace 1 or 2  
also not sure why an A= unit is needed in a bathroom..

Richard Kahn  
HBRK Asso=iates Inc.  
575 Lexington Avenue 4th Floor  
New York, NY 10022

[REDACTED]  
[REDACTED]  
[REDACTED] >

Begin forwarded message:

From: bri=e gordon <[REDACTED]> <[REDACTED]> >

Subject: Re: LSJ Sta=f Cottage

Date: April 17, 2017 at 10:15:23 AM =DT

To: ?=AORich Kahn <[REDACTED]> <[REDACTED]> >  
=/div>

Cc: <=pan style="font-family:-webkit-system-font,'Helvetica Neue',Helv=tica,sans-serif">LSJ GSJ

[REDACTED]  
[REDACTED]  
[REDACTED]

Rich

Reference E mail dated Apr 13th  
=ttached Proposal is for the Staff cottage Bathroom Mini Spilt,  
t=tal cost to replace all 3 Mini Spilt units is \$14124.50

Can we proceed

=div dir="ltr">

On Thu, Apr 13, 2017 at 9:35 AM, Brice Gordon <[REDACTED]> <mailto:bgordon.lsj@gmail.com> >  
wrote:

Rich

attached photos and proposals to replace the existing mini split AC units in the LSJ Staff Cottage, it does not include Bathroom AC which also needs to be replaced  
Reefco missed Bathroom unit and will be forwarding separate proposal, cost should be a little less as it is a smaller unit

<div>These units are in very bad condition, missing filters, covers etc

Can we proceed with replacement

Regards

Brice

--

Brice Gordon

= [REDACTED] >

Begin forwarded message:

From: Brice Gordon <[REDACTED]>

Subject: LSJ Staff Cottage

Date: April 13, 2017 at 10:35:33 AM EDT

To: Rich Kahn <[REDACTED]> <[REDACTED]>

Rich

attached photos and proposals to replace the existing mini split AC unit in the LSJ Staff Cottage, it does not include Bathroom AC which also needs to be replaced  
Reefco missed Bathroom unit and will be forwarding separate proposal, cost should be a little less as it is a smaller unit

These units are in very bad condition, missing filters, covers etc

Can we proceed with replacement

Regards

Brice  
</div>

conversation-id 46266 date-last-viewed 0 date-received 1493138854 flags 8590195713 gmail-label-ids 7 remote-id 708267